


PARTICLE SIZE DISTRIBUTION REPORT



<p>Client: Glendon Quarry Pty Ltd</p> <p>Client Address: PO Box 771, Glendon Road , Anakie</p> <p>Project: Compliance Testing - Glendon Quarry</p> <p>Location: Glendon Road, Anakie</p> <p>Component:</p> <p>Area Description:</p>	<p>Report Number: 1692/R/8117-1</p> <p>Project Number: 1699/P/5</p> <p>Lot Number:</p> <p>Internal Test Request: 1692/T/2820</p> <p>Client Reference/s: 30/03/2016</p> <p>Report Date / Page: 1/04/2016 Page 1 of 1</p>
---	--

Test Procedures: Q103A									
<p>Sample Number: 1692/S/17030</p> <p>Sampling Method: AS1289.1.2.1 Cl 6.4a</p> <p>Date Sampled: 30/03/2016</p> <p>Sampled By: client</p> <p>Date Tested: 31/03/2016</p> <p>Material Source: Glendon Quarry</p>	<p style="text-align: center;">Sample Location</p> <table style="width: 100%;"> <tr> <td style="width: 50%;">Location</td> <td style="width: 50%;">Stockpile at Quarry</td> </tr> <tr> <td></td> <td style="text-align: center;">-</td> </tr> <tr> <td></td> <td style="text-align: center;">-</td> </tr> <tr> <td></td> <td style="text-align: center;">-</td> </tr> </table> <p>Material Type: 20mm Concrete Aggregate</p>	Location	Stockpile at Quarry		-		-		-
Location	Stockpile at Quarry								
	-								
	-								
	-								

AS Sieve (mm)	Specification Minimum	Percent Passing (%)	Specification Maximum
19.0		100	
16.0		76	
13.2		33	
9.5		1.5	
2.36		0.2	



Remarks

	<p>The results of the tests, calibrations and/or measurements included in this document are traceable to Australian/national standards. Accredited for compliance with ISO/IEC 17025</p> <p>Accreditation Number: 1986 Corporate Site Number: 1692</p>	 <p>Approved Signatory: Donna Marr Form ID: W9Rep Rev 2</p>
--	--	--